

25X1

**Page Denied**

Next 1 Page(s) In Document Denied

Exit onto concrete platform,  
5 steps down to ground  
level.

Fence with gate; gate  
normally closed

25X1

# CONFIDENTIAL INFORMATION REPORT

OPNAV FORM 3820-2 (C) (REV. 6-55)

CLASSIFICATION

FROM

REPORT NO.

DATE

CONFIDENTIAL

20 July 1959

25X1

Check point, room 6x12',  
building has 2 floors

Pump exposed here, size unknown.

Water fittings. Hose has  
to be led out across pier.

Floodlights

vessel

25X1

Most of fittings is within a  
raised concrete "island". Walk-  
way over this is approached by  
concrete steps at either end.  
Walkway is steel plate.

25X1

Long, continuous iron plate, flush  
with pier level. [redacted]  
petroleum lines run underneath this  
because at frequent intervals a  
portion of the plates would be  
lifted by a worm checking some-  
thing underneath. Extent of plating  
unknown toward end of pier.

Pier length 1000'

30'

gate

Floodlights

small house

CLASSIFICATION

CONFIDENTIAL

From a U.S.S.R. chart of 1934

Scale 1:30,000

